


Caerus
PJ 16
Location ID: 334656



Well heads



Entrance to location

Caerus
PJ 16
Location ID: 334656



Lack of location signage



Lack of location signage

Caerus
PJ 16
Location ID: 334656



Tank battery



Battery signage is lacking 911

Caerus
PJ 16
Location ID: 334656



Unknown equipment and production equipment



Chemical tank

Caerus
PJ 16
Location ID: 334656



Chemical tank containment full of fluid



Well heads

Caerus
PJ 16
Location ID: 334656



Unknown equipment tied to a PVC pipe at separators.



Unknown equipment tied to a PVC pipe at separators.

Caerus
PJ 16
Location ID: 334656



Unknown equipment tied to a PVC pipe at separators.



Unknown equipment tied to a PVC pipe at separators.

Caerus
PJ 16
Location ID: 334656



Areas of location lack stabilization



All signage is lacking 911