

Caerus  
PD 21  
Location ID: 334732



Location entrance signage



Production equipment



Caerus  
PD 21  
Location ID: 334732



Production equipment



Tank battery



Caerus  
PD 21  
Location ID: 334732



Tank battery lacking proper signage



Tank battery lacking proper signage



Caerus  
PD 21  
Location ID: 334732



Well heads



Well heads



Caerus  
PD 21  
Location ID: 334732



Open pipe for wildlife



Chemical tank containment full of fluid