

Inspection Photos

API: 071-09856

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 8/29/2023



Inspection Photos



Photo 1. Facing east toward the access road. A recent heavy rainstorm has washed sediment and debris onto the road and gate.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 071-09856 | Date: 8/29/2023

Inspection Photos



Photo 2. Facing northeast along the access road. Stormwater has washed down the access road causing erosion.



Inspection Photos

Aug 29, 2023 at 10:11:14 AM



Photo 3. Facing southeast toward the well site.

