

Inspection Photos

API: 071-07252

Operator: OGRIS OPERATING LLC

Inspection Date: 8/21/2023



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

API: 071-07252 | Date: 8/21/2023

Inspection Photos

Aug 21, 2023 at 9:56:20 AM



Photo 1. Facing southeast toward the wellsite.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 071-07252 | Date: 8/21/2023

Inspection Photos



Photo 2. Facing toward the well. There is a dripping leak at the wellhead.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 071-07252 | Date: 8/21/2023