

# Inspection Photos

ID: 333719

Operator: OGRIS OPERATING LLC

Inspection Date: 8/21/2023



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

ID: 333719 | Date: 8/21/2023

## Inspection Photos



**Photo 1.** Facing southwest along the main access road at Lat/Long: 37.01620,-104.89531. There is erosion along this area which needs to be controlled.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

ID: 333719 | Date: 8/21/2023

## Inspection Photos



**Photo 2.** Facing northeast along the main access road at Lat/Long: 37.01620,-104.89531. There is erosion along this area which needs to be controlled.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

ID: 333719 | Date: 8/21/2023

## Inspection Photos



**Photo 3.** Facing south along the main access road. This area was graded and vegetation is establishing. Additional BMP's such as check dams may be needed to prevent erosion.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

ID: 333719 | Date: 8/21/2023

## Inspection Photos



**Photo 4.** Facing southeast at Lat/Long: 37.01055, -104.89653. A culvert was installed at this area of the road. Disturbed soils need to be seeded and stabilized.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

ID: 333719 | Date: 8/21/2023

## Inspection Photos



**Photo 5.** Facing southeast at Lat/Long:37.01055,-104.89653. A culvert was installed at this area of the road. Disturbed soils need to be seeded and stabilized.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

ID: 333719 | Date: 8/21/2023

## Inspection Photos



**Photo 6.** The culvert outlet is half full of sediment and needs to be cleaned out. A sediment trap could be beneficial to contain erosion.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

ID: 333719 | Date: 8/21/2023

Inspection Photos



**Photo 7.** Facing toward the wellsite.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

ID: 333719 | Date: 8/21/2023