

Final Reclamation and Stormwater Inspection

Date: 08/23/2023

Operator: SCHNEIDER ENERGY SERVICES - 76840

Location ID: 313900

Inspection Document #: 708200522

Morgan County, CO

SWSW Section 7 T6N R60W

Dylan Edwardson
Reclamation Specialist, ECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos
Location Name: Knappe 3
Location ID: 313900



Photo 1. Facing west at the former location. The reclaimed portions of the location do not appear to be progressing towards Rule 1004 standards and rules with evidence of bare/exposed soils and non-uniform crop growth observed during this inspection.

Inspection Photos
Location Name: Knappe 3
Location ID: 313900



Photo 2. Facing north; see comments in Photo 1.

Inspection Photos
Location Name: Knappe 3
Location ID: 313900



Photo 3. Facing east; see comments in Photo 1.

Inspection Photos
Location Name: Knappe 3
Location ID: 313900



Photo 4. Facing south; see comments in Photo 1.

Inspection Photos
Location Name: Knappe 3
Location ID: 313900



Photo 5. Overview of the former location; debris and equipment remain on location.