

Inspection Photos
Location Name: HSR-Henderson 4-11A
Location ID: 331205



Photo 1 Location access overgrown with undesirable vegetation.



Photo 2 Location ROW overgrown with undesirable vegetation.

Inspection Photos
Location Name: HSR-Henderson 4-11A
Location ID: 331205



Photo 3 WH/sign.

