

Inspection Photos
Location Name: Lamb-Dalton Nessu 13
Location ID: 317947



Colorado Energy & Carbon Management Commission
40.12172, -104.80745, 4812.9ft
08/31/2023 10:30:50



Colorado Energy & Carbon Management Commission
40.12168, -104.80764, 4865.7ft
08/31/2023 10:03:22

Photo 3 WH/BOP

Photo 4 Location.

Inspection Photos
Location Name: Lamb-Dalton Nesssu 13
Location ID: 317947




Photo 5 Casing pressure gauge at 400 psi. 5 minute mark.

Photo 6 Casing pressure gauge at 400 psi. post test.

Inspection Photos

Location Name: Lamb-Dalton Nessu 13

Location ID: 317947



Colorado Energy & Carbon Management Commission
 40.12174, -104.80743, 4751.5ft
 08/31/2023 10:52:10

Photo 7 Form 21.