



Inspection Photos
well 057-06280

Inspection
Date:8/18/2023

All Photos taken
by Kris Neidel

Photo #1 Overview of the location. It is not obvious where this well produces to. There is a buried poly flowline at the wellhead, it appears that the well produces to a tank at the 3x Location. The tank at the 3x does not identify the 12-1. There is an irrigation ditch ~100ft to the east of the well pad. The well is accessible by vehicle. Well was SI at time of inspection.



Inspection Photos
well 057-06280

Inspection
Date:8/18/2023

All Photos taken
by Kris Neidel

Photo #2 Fenced wellhead and pumping unit. Some tubing on the ground near well.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection Photos
well 057-06280

Inspection
Date:8/18/2023

All Photos taken
by Kris Neidel

Photo #3 sign at well.



Inspection Photos
well 057-06280

Inspection
Date:8/18/2023

All Photos taken
by Kris Neidel

Photo #4 wellhead



Inspection Photos
well 057-06280

Inspection
Date:8/18/2023

All Photos taken
by Kris Neidel

Photo #5 marker on well.