

# Inspection Photos

8/21/2023

Operator: CAERUS PICEANCE LLC #10456

Location Number: 478266

Garfield County, CO

Aaron Trujillo  
NW Reclamation Specialist  
CECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location Number: 478266



August 21, 2023



August 21, 2023

**Photo 1:** Location overview.



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location Number: 478266



**Photo 2:** Stained soils around equipment appear to have been cleaned.



## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location Number: 478266



**Photo 3:** Sediment traps on Location remain unchanged; unable to find evidence that corrective actions have been taken.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location Number: 478266



**Photo 4:** BMPs remain missing or insufficient to minimize erosion and degradation on the fill slopes.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location Number: 478266



**Photo 5:** BMPs remain missing or insufficient to minimize erosion and degradation on the cut slopes.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location Number: 478266



**Photo 6:** Photos examples showing drain pipes per the Form 2A Location drawing/SWMP have not been installed.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location Number: 478266



**Photo 7:** Stormwater ditch. BMPs per the Location Drawing / SWMP not observed.



## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location Number: 478266



**Photo 8:** Drill cuttings area. Impacts remain apparent to the WPS. BMPs to mitigate impacts not apparent.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location Number: 478266



**Photo 9:** Spill on fill slope appears to have been cleaned. Stormwater and erosion control measures on the fill slope remain missing or insufficient.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location Number: 478266



**Photo 10:** Material spills on the WPS remain apparent.



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location Number: 478266



**Photo 11:** Improper material covering.



## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location Number: 478266



**Photo 12:** VTC installed at Location entrance.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location Number: 478266



**Photo 13:** Location signage at entrance per 605 rules remain missing.



## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location Number: 478266



**Photo 14:** Photo taken from the access road on the west end of the Location. Photo shows stormwater runoff has resulted in erosion, degradation and off-site sediment transport; Stormwater and erosion control measures inadequate.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location Number: 478266



**Photo 15:** Photo taken from the access road on the west end of the Location. Photo shows stormwater runoff has resulted in erosion, degradation and off-site sediment transport; Stormwater and erosion control measures inadequate.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources