

Inspection Photos

8/21/2023

Operator: CAERUS PICEANCE LLC #10456

Location Number: 479214

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location Number: 479214



Photo 1: Location overview.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location Number: 479214



Photo 2: Battery facility signage installed. Signage on tanks not observed.

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location Number: 479214



Photo 3: Photos examples showing interim areas; overall status of reclamation is “in process”.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location Number: 479214



Photo 4: Example of trash debris on Location.

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location Number: 479214



Photo 5: Example of trash debris on Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources