

# Inspection Photos

8/21/2023

Operator: CAERUS PICEANCE LLC #10456

Location Number: 335928

Garfield County, CO

Aaron Trujillo  
NW Reclamation Specialist  
CECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location Number: 335928



August 21, 2023



August 21, 2023

**Photo 1:** Working Pad overview.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location Number: 335928



**Photo 2:** Signage at the tank battery not posted, or not conspicuous.



## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location Number: 335928



**Photo 3:** Photos examples showing Noxious weeds (Musk thistle, Bull thistle) observed establishing on the interim areas.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location Number: 335928



**Photo 4:** Photos examples showing Noxious Weeds (Spotted Knapweed) establishing on the interim areas of the Location.



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location Number: 335928



**Photo 5:** Photos examples showing Noxious Weeds (Musk thistle, Spotted Knapweed) establishing along the access road.



## Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location Number: 335928



**Photo 6:** Photos examples showing Noxious Weeds (Musk thistle) establishing along the access road.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources