

Inspection Photos
Location Name: Washburn GX 15-62HN
Location ID: 428699



Photo 1 – Wellheads



Photo 2 – Weeds at ECD have been cut down



Inspection Photos
Location Name: Nelson Ranches A-1
Location ID: 326962



Photo 3 – Tumbleweed at South Separator



Photo 4 – Weeds have been cut down

Inspection Photos
Location Name: Nelson Ranches A-1
Location ID: 326962



Photo 5 – Tank Battery