

## Inspection Photos

Location Name: CAERUS PICEANCE LLC BENZEL K25 Pad

Location #: 335344



Aug 31, 2023 at 11:41:44 AM  
CO

**Photo # 7891 From entrance to location**



Aug 31, 2023 at 11:42:28 AM  
CO

**Photo # 7892 Location**

**Inspection Photos**  
**Location Name: CAERUS PICEANCE LLC BENZEL K25 Pad**  
**Location #: 335344**



**Photo # 7893 Location**



**Photo # 7894 Location**



**Inspection Photos**  
**Location Name: CAERUS PICEANCE LLC BENZEL K25 Pad**  
**Location #: 335344**



**Photo # 7895 BENZEL 25-11 bradenhead line open to atmosphere**



**Photo # 7912 BENZEL 25-11 bradenhead line shut in at 2 inch ball valve by Caerus employee. Please refer to equipment section of FIR for more information.**



## Inspection Photos

Location Name: CAERUS PICEANCE LLC BENZEL K25 Pad

Location #: 335344



**Photo # 7908 Flowline heating insulation open ended**



**Photo # 7911 Flowline heating insulation no longer open ended, capped by Caerus employee. Please refer to equipment section of FIR for more information.**