

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403516244

Date Received:

08/30/2023

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

General

sjninspections@ikavenergy.com

Labowskie, Steve

steve.labowskie@state.co.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 712700563

Inspection Date: 08/22/2023

FIR Submit Date: 08/22/2023

FIR Status: _____

Inspected Operator Information:

Company Name: SIMCOE LLC

Company Number: 10749

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

LOCATION - Location ID: 325517

Location Name: DAVIS-N35N8W Number: 28SWNE County: LA PLATA

Qtrqtr: SWNE Sec: 28 Twp: 35N Range: 8W Meridian: N

Latitude: 37.275238 Longitude: -107.749781

FACILITY - API Number: 05-067- -00 Facility ID: 214931

Facility Name: DAVIS Number: 01-28 1

Qtrqtr: SWNE Sec: 28 Twp: 35N Range: 8W Meridian: N

Latitude: 37.275238 Longitude: -107.749781

CORRECTIVE ACTIONS:

1 ☒ CA# 179239

Corrective Action: Mark guy anchors or remove if non-serviceable or no longer needed for ongoing oil and gas operations.

Date: 09/05/2023

Response: CA COMPLETED

Date of Completion: 08/29/2023

Operator Comment: Marked rig anchor on location.

COGCC Decision:

Date Run: 9/5/2023 Doc [#403516244]

Page 1 of 2

CA complete. See attached photos.

Print Name: Grace Bryson Signed: _____

Title: Permitting Specialist I

<u>Document Number</u>	<u>Description</u>
403516244	FIR RESOLUTION SUBMITTED
403516249	Davis 1-28 1, CA complete photos