

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/4NENW

Location ID: 334832

Date: 8/24/2023



South Entrance to Location – Photo #06103



North End of Location – Photo #06104

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/4NENW

Location ID: 334832

Date: 8/24/2023



Wellheads – Photo #06109



Separators – Photo #06106

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/4NENW

Location ID: 334832

Date: 8/24/2023



Tank Battery – Photo #06105



Unsecured Separator Hatch – Photo #06107

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-67S96W/4NENW

Location ID: 334832

Date: 8/24/2023



Access Road Degradation – Photo #06110



Access Road Degradation – Photo #06111