

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON/MV 24-20

Location ID: 335262

Date: 8/28/2023



East Entrance to Location – Photo #06196



Wellheads – Photo #06197

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON/MV 24-20

Location ID: 335262

Date: 8/28/2023



Separators/Site Degradation – Photo #06199



Tank Battery – Photo #06200

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON/MV 24-20

Location ID: 335262

Date: 8/28/2023



Site Degradation From Stormwater Event – Photo #06198



Site Degradation From Stormwater Event – Photo #06201