

Inspection Photos
Location Name: Taylor No. 2 #32-1
API: 05-067-06542



Taylor No. 2 #32-1 location photo.



Close up of Taylor No. 2 #32-1 well head.

Inspection Photos
Location Name: Taylor No. 2 #32-1
API: 05-067-06542



Pit feature southeast of well head.



Flow line and valve daylighting in pit.