

Inspection Photos
Location Name: Luhman 6-4-4
Location ID: 306167



Photo 1 Location.

Photo 2 Undesirable vegetation around WH/sign.

Inspection Photos
Location Name: Luhman 6-4-4
Location ID: 306167



Photo 3 TB/sign.

Photo 4 Undesirable vegetation inside TB berm.

Inspection Photos
Location Name: Luhman 6-4-4
Location ID: 306167



Photo 5 Undesirable vegetation inside TB berm.

Photo 6 Undesirable vegetation inside TB berm.

Inspection Photos
Location Name: Luhman 6-4-4
Location ID: 306167



Colorado Energy & Carbon Management Commission
40.16716, -104.8919, 4855.4ft
08/29/2023 13:23:26

Photo 7 Pig station.



Colorado Energy & Carbon Management Commission
40.16718, -104.892, 4853.6ft
08/29/2023 13:23:36

Photo 8 ECD, Gas Meter Run & 2 HHS.