

Inspection Photos
Location Name: Kortum 2
Location ID: 319823



Photo 1 Location, undesirable vegetation growing tall around location ROW & along the access road.



Photo 2 WH sign.



Inspection Photos
Location Name: Kortum 2
Location ID: 319823



Photo 3 PA well excavation.



Photo 4 Flow line excavation between TB & WH.

Inspection Photos
Location Name: Kortum 2
Location ID: 319823



Photo 5 Access road sediment washing off location.



Photo 6 Access road sediment washing off location.

Inspection Photos
Location Name: Kortum 2
Location ID: 319823



Photo 7 Pump Jack.



Photo 8 Access road sediment washing off location.

Inspection Photos
Location Name: Kortum 2
Location ID: 319823



Colorado Energy & Carbon Management Commission
39.9544, -104.89365, 5158.3ft
09/05/2023 12:54:17



Colorado Energy & Carbon Management Commission
39.9544, -104.89378, 5170.4ft
09/05/2023 12:54:30

Photo 9 Flow line excavation between TB & WH.

Photo 10 TB sign.

Inspection Photos
Location Name: Kortum 2
Location ID: 319823



Photo 11 Flow line excavation.



Photo 12 Flow line excavation.

Inspection Photos
Location Name: Kortum 2
Location ID: 319823



Photo 13 Construction fencing in disrepair.



Photo 14 Heated Vertical Separator.