

Inspection Photos
Location Name: THISTLE DOWN B/31-20D
Location #: 302630



Photo #1

Thistle Down B 31-22D (123-30789) Wellsite
Plugged & Abandoned | PA
Plugging Ops: Cementing: Cmt to surface



Photo #2

Thistle Down B 31-22D Wellsite
Plugged & Abandoned | PA
Plugging Ops: Cementing: Cmt to surface
~ 10' below top



Inspection Photos
Location Name: THISTLE DOWN B/31-20D
Location #: 302630



Photo #3

Thistle Down B 31-22D Wellsite
Plugged & Abandoned | PA
Plugging Ops: Cementing: Cmt to surface
Site safety signage



Photo #4

Thistle Down B 31-22D Wellsite
Plugged & Abandoned | PA
Plugging Ops: Cementing: Cmt to surface
Wellsite entrance signage



Inspection Photos
Location Name: THISTLE DOWN B/31-20D
Location #: 302630




Photo #5

Thistle Down B 31-22D Wellsite
Plugged & Abandoned | PA
Plugging Ops: Cementing: Cmt to surface
JSA: 2023-09-05



Photo #6

Thistle Down B 31-22D Battery site
Plugged & Abandoned | PA
Plugging Ops: Cementing: Cmt to surface
Battery sign

