

# Interim & Stormwater Reclamation Inspection

August 16, 2023

Operator: Helena Resources Inc #10457

Location ID: 3204260

Inspection Document #:709400458

Weld, County

NWSW Section 6, 1S67W

Reed Wold  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Bredechoft 13-6  
Location ID: 320425




Photo 1. Photo taken of location sign.

Photo 2. Photo of tank battery





**Inspection Photos**  
**Location Name: Bredechoft 13-6**  
**Location ID: 320425**



**Photo 3. Photo taken of access road lined with weeds (Kosah).**



**Photo 4. Photo of open dumpster on site surrounded in tall weeds (Kosha)**



**Inspection Photos**  
**Location Name: Bredechoft 13-6**  
**Location ID: 320425**



**Photo 5. Photo taken of reclaimed area, covered in weeds( kosha, tumble weeds and cheatgrass).**



**Photo 6. Photo of trash on site near separator.**