

Interim & Stormwater Reclamation Inspection

August 16, 2023

Operator: Helena Resources Inc #10457

Location ID: 05-001-09291

Inspection Document #:709400464

Weld, County

NWSW Section 6, 1S67W

Reed Wold
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Bredechoft 13-6
Location ID: 320425



Photo 1. Photo taken of location sign.

Photo 2. Photo of wellhead



Inspection Photos
Location Name: Bredechoft 13-6
Location ID: 320425



Photo 3. Photo taken of reclaimed area around wellhead weeds observed.



Photo 4. See photo 3 comments

Inspection Photos
Location Name: Bredechoft 13-6
Location ID: 320425



Photo 5. Photo taken of reclaimed area, and tank on site, covered in tall weeds (kosha, tumble weeds and cheatgrass).



Photo 6. See photo 5 comments.

