

Interim & Stormwater Inspection

August 16, 2023

Operator: KP Kauffman Co, # 46290

Location ID: 331008

Inspection Document # 709400497

Weld, CO

NWSW, 32 1N 67W

Reed Wold
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: Jacobucci 13 23-32

Location ID: 331008



Photo 1. Photo of location sign on site.



Photo 2. Photo of tank battery.

Inspection Photos

Location Name: Jacobucci 13 23-32

Location ID: 331008



Photo 3. Photo of trash and weeds (kosha) on site, facing east



Photo 4. Photo of trash and weeds (kosha) on site, facing northwest.

Inspection Photos

Location Name: Jacobucci 13 23-32

Location ID: 331008



Photo 5. Photo of weeds (kosha) on site facing northwest.



Photo 6. Photo of staining from leaking equipment on site facing west.