

Interim & Stormwater Inspection

August 16, 2023

Operator: KP Kauffman Co, # 46290

Location ID: 318728

Inspection Document # 709400499

Weld, CO

SESE, 32 1N 67W

Reed Wold
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: Jacobucci 4

Location ID: 318728



Photo 1. Photo of location sign on site.



Photo 2. Photo of well head.

Inspection Photos

Location Name: Jacobucci 4

Location ID: 318728



Photo 3. Photo of trash under well head.



Photo 4. Photo of weeds (goathead) on site.

Inspection Photos

Location Name: Jacobucci 4

Location ID: 318728



Photo 5. Photo of weeds (kosha) on site facing northeast.



Photo 6. Photo of weeds (kosha, cheatgrass, & goathead) on site facing west.