

Interim & Stormwater Inspection

August 16, 2023

Operator: KP Kauffman Co, # 46290

Location ID: 317904

Inspection Document # 709400511

Weld, CO

SENW, 32 1N 67W

Reed Wold
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: David Howard #3

Location ID: 317904



Photo 1. Photo of location sign on site.



Photo 2. Photo of well head.

Inspection Photos

Location Name: David Howard #3

Location ID: 317904



Photo 3. Photo of weeds (Kosha) on site, and mowed vegetation around site facing Northwest



Photo 4. See photo 3 comments.

Inspection Photos

Location Name: David Howard #3

Location ID: 317904



Photo 5. Photo of weeds (kosha & cocklebur) at well head..



Photo 6. Photo of weeds (kosha) on site facing southwest.