

Interim & Stormwater Inspection

August 16, 2023

Operator: KP Kauffman Co, # 46290

Location ID: 318676

Inspection Document # 709400513

Weld, CO

SWNW, 32 1N 67W

Reed Wold
Reclamation Specialist, COGCC



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: David Howard #6

Location ID: 318676



Photo 1. Photo of location sign on site.



Photo 2. Photo of well head.

Inspection Photos

Location Name: David Howard #6

Location ID: 318676



Photo 3. Photo of weeds (Kosha) on site, facing southeast



Photo 4. Photo of weeds (kosha) on site facing north.

Inspection Photos

Location Name: David Howard #6

Location ID: 318676



Photo 5. Photo of weeds (kosha) at well head facing south