

Inspection Photos

Location Name: TREBOR B-65N64W/11NWNE

Location ID: 310600



Photo #1

Trebor B 11-17 (123-26658) Wellsite

Temporarily Abandoned | TA

*CA: Overgrown vegetation, needs mitigated.
prior photo*



Photo #2

Trebor B 11-17 Wellsite

Temporarily Abandoned | TA

*Overgrown vegetation, NOW mitigated
Date: 07-28-2023 (Operator photo)*



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: TREBOR B-65N64W/11NWNE

Location ID: 310600



Photo #3

Trebor B 11-17 Wellsite

Temporarily Abandoned | TA

Overgrown vegetation, NOW mitigated

Date: 07-28-2023 (Operator photo)



Photo #4

Trebor B 11-17 Wellsite

Temporarily Abandoned | TA

Overgrown vegetation, NOW mitigated

Date: 07-28-2023 (Operator photo)



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: TREBOR B-65N64W/11NWNE

Location ID: 310600



Photo #5

Trebor B11-8, 11-17 Battery site

Inactive | Shut-down

Equipment Documented; Loc ID: 323710

prior photo



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources