

**Inspection Photos**  
**Location Name: TREBOR B/11-22**  
**Location ID: 414327**



**Photo #1**

**Trebor B 11-22 (123-30733) Wellsite**

**Temporarily Abandoned | TA**

*CA: Overgrown vegetation, needs mitigated.  
prior photo*



**Photo #2**

**Trebor B 11-22 Wellsite**

**Temporarily Abandoned | TA**

*Overgrown vegetation, NOW mitigated  
Date: 07-28-2023 (Operator photo)*



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

**Inspection Photos**  
**Location Name:** TREBOR B/11-22  
**Location ID:** 414327



**Photo #3**  
**Trebor B 11-22 Battery site**  
**Inactive | Shut-down**  
*prior photo*



**Photo #4**  
**Trebor B 11-22 Battery site**  
**Inactive | Shut-down**  
**Tank(s): SE corner**  
*prior photo*





**Inspection Photos**  
**Location Name: TREBOR B/11-22**  
**Location ID: 414327**



**Photo #5**

**Trebor B 11-22 Battery site**

**Inactive | Shut-down**

**Separator(s), ECD(s)**

*prior photo*



**Photo #6**

**Trebor B 11-22 Battery site**

**Inactive | Shut-down**

**Battery sign**

*prior photo*

