

## Inspection Photos

Location Name: VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/13NWNW

Location ID: 312601

Date: 9/6/2023



**SW Corner of Location – Photo #06218**



**Wellhead/Weeds/Inaccurate Sign – Photo #06228**

## Inspection Photos

Location Name: VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/13NWNW

Location ID: 312601

Date: 9/6/2023



**Separator/Gas Meter/Wildlife Entry Hazard/Weeds – Photo #06229**



**Tank Battery/Weeds – Photo #06231**

## Inspection Photos

Location Name: VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/13NWNW

Location ID: 312601

Date: 9/6/2023



Storage of Unused Equipment – Photo #06224



Storage of Unused Equipment/Weeds – Photo #06222

## Inspection Photos

Location Name: VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/13NWNW

Location ID: 312601

Date: 9/6/2023



Storage of Unused Equipment/Wildlife Entry Hazard – Photo #06221



Storage of Unused Equipment/Weeds – Photo #06223

## Inspection Photos

Location Name: VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/13NWNW

Location ID: 312601

Date: 9/6/2023



Storage of Unused Equipment/Weeds – Photo #06225



Storage of Unused Equipment/Weeds – Photo #06226

## Inspection Photos

Location Name: VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/13NWNW

Location ID: 312601

Date: 9/6/2023



**Debris/Weeds – Photo #06227**



**Location Lacks Stabilization – Photo #06232**

## Inspection Photos

Location Name: VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/13NWNW

Location ID: 312601

Date: 9/6/2023



**Insufficient Vehicle Tracking BMPs at Location  
Entrance/Exit – Photo #06234**



**Access Road Erosion – Photo #06235**

## Inspection Photos

Location Name: VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/13NWNW

Location ID: 312601

Date: 9/6/2023



Access Road Erosion – Photo #06236