

Inspection Photos

API: 099-06224

Operator: RENEGADE OIL & GAS COMPANY

Inspection Date: 9/6/2023



Inspection Photos



Photo 1. Facing southwest toward the offsite meter shed and separator.



Inspection Photos



Photo 2. Facing toward the wellsite located in a cultivated field.

