

# Interim Reclamation and Stormwater Inspection

Date: 09/05/2023

Operator: YOUNG GAS STORAGE COMPANY LTD -  
98220

Location ID: 313960

Inspection Document #: 708200541

Morgan County, CO

NENE Section 11 T4N R58W

Dylan Edwardson  
Reclamation Specialist, ECMC



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: Young 45  
Location ID: 313960



**Photo 1.** Taken from the southern portion of the location. The interim areas are predominantly undesirable vegetation (e.g. kochia and russian thistle). Additional management of weeds and interim reclamation activities are required.

Inspection Photos  
Location Name: Young 45  
Location ID: 313960



**Photo 2.** See comments in Photo 1.



**Photo 3.** Concrete structures on location do not appear to be used and require removal per Rule 606.

Inspection Photos  
Location Name: Young 45  
Location ID: 313960



**Photo 4.** Colorado List B Noxious Weed- Scotch Thistle- observed on location that requires management to prevent spread onto adjacent land.

Inspection Photos  
Location Name: Young 45  
Location ID: 313960



**Photo 5.** Rill erosion degradation occurring on the access roads. No apparent stormwater controls/BMPs were observed to prevent sediment from exiting off location.

Inspection Photos  
Location Name: Young 45  
Location ID: 313960



Photo 6. Continued from Photo 5.

Inspection Photos  
Location Name: Young 45  
Location ID: 313960



Photo 7. See comments in Photo 5.



**Photo 8.** Day tank without legible labels and no wildlife protection/exclusion device installed around secondary containment.



**Photo 9.** NFPA placard is faded/peeling/cracked and requires replacement.

Inspection Photos  
Location Name: Young 45  
Location ID: 313960



**Photo 10.** Bullet casing observed on the center/eastern portion of the location. Operator shall remove debris and it's advised posting against such activities on an active location.