

Inspection Photos
Location Name: CAERUS PICEANCE LLC H23NW Pad
Location #: 335444



Photo # 8612 From entrance to location



Photo # 8614 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC H23NW Pad
Location #: 335444



Photo # 8615 Location



Photo # 8616 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC H23NW Pad
Location #: 335444



Photo # 8617 Location




Photo # 8628 Stained gravel in secondary containment

Inspection Photos

Location Name: CAERUS PICEANCE LLC H23NW Pad

Location #: 335444



Photo # 8630 Stained soils & gravel (near pig station)