

## Inspection Photos

Location Name: TEP Rocky Mountain LLC CLOUGH RWF 533-19 Pad

Location # 335368



Photo # 8491 From entrance to location



Photo # 8492 Location

## Inspection Photos

Location Name: TEP Rocky Mountain LLC CLOUGH RWF 533-19 Pad

Location # 335368



Sep 7, 2023 at 9:46:44 AM  
CO

Photo # 8493 Location



Sep 7, 2023 at 9:46:59 AM  
CO

Photo # 8494 Location



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



## Inspection Photos

Location Name: TEP Rocky Mountain LLC CLOUGH RWF 533-19 Pad

Location # 335368



Photo # 8496 Debris (SE corner of location)