

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 136 Pad

Location ID: 322444



Photo # 8516 From entrance to location



Photo # 8517 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 136 Pad

Location ID: 322444



Photo # 8518 Location



Photo # 8519 Location



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 136 Pad

Location ID: 322444




Photo # 8520 Location



Photo # 8536 Location



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 136 Pad

Location ID: 322444



Photo # 3158 From inspection 708901066 conducted on 07/17/2023 Unmarked deadman/anchor



Photo # 8522 Unmarked deadman/anchor

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 136 Pad

Location ID: 322444



Photo # 3157 From inspection 708901066 conducted on 07/17/2023 Same unmarked deadman/anchor from a different angle



Photo # 8527 Same unmarked deadman/anchor from a different angle