

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DOE 1-M-19 Pad

Location ID: 311545



Photo # 8436 From entrance to location



Photo # 8437 Location

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DOE 1-M-19 Pad

Location ID: 311545



Photo # 8438 Location

Photo # 8439 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DOE 1-M-19 Pad

Location ID: 311545



Photo # 8445 Open ended load line



Photo # 8446 Open ended load line

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DOE 1-M-19 Pad

Location ID: 311545



Sep 7, 2023 at 9:19:26 AM  
CO



Sep 7, 2023 at 9:20:02 AM  
CO


**Photo # 8447 Weeds/undesirable plant species in secondary containment**

**Photo # 8448 Weeds/undesirable plant species in secondary containment**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DOE 1-M-19 Pad

Location ID: 311545



**Photo # 8450 Weeds/undesirable plant species in secondary containment**



**Photo # 8452 Weeds/undesirable plant species in secondary containment**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DOE 1-M-19 Pad

Location ID: 311545



**Photo # 8457 Weeds/undesirable plant species in secondary containment**



**Photo # 8459 Weeds/undesirable plant species in secondary containment**