

Inspection Photos
Location Name: Wattenburg Henry E UT B2
Location ID: 332979



Photo 1 well sign

Photo 2 pumping unit consider unused equipment and overgrown vegetation

Inspection Photos
Location Name: Wattenburg Henery E UT B2
Location ID: 332979



Photo 3 overgrown vegetation

Photo 4 mechanical equipment in disrepair, no motor