

Inspection Photos

Location Name: VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/7NWSE

Location ID: 323851

Date: 9/6/2023



SE Corner of Location – Photo #06287



SW Corner of Location – Photo #06288

Inspection Photos

Location Name: VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/7NWSE

Location ID: 323851

Date: 9/6/2023



Wellhead – Photo #06292



Separator/Weeds – Photo #06296

Inspection Photos

Location Name: VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/7NWSE

Location ID: 323851

Date: 9/6/2023



Tank Battery/Weeds – Photo #06289



Unused Equipment Stored on Location/Weeds – Photo #06293

Inspection Photos

Location Name: VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/7NWSE

Location ID: 323851

Date: 9/6/2023



Stuffing Box Leak/Stained Soil – Photo #06295



Secondary Containment Berm Damaged – Photo #06290