

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM Cuttings Trench/246-1

Location ID: 334895

Date: 9/7/2023



Wellheads – Photo #06325



Separators – Photo #06327

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM Cuttings Trench/246-1

Location ID: 334895

Date: 9/7/2023



Tank Battery – Photo #06326



Access Road Lacks Stabilization – Photo #06329

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM Cuttings Trench/246-1

Location ID: 334895

Date: 9/7/2023



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #06330**