

# Interim Reclamation and Stormwater Inspection

August 23, 2023

Operator: KP KAUFFMAN COMPANY INC - 46290

Location ID: 319144

Inspection Document #: 697504810

Weld County, CO

SWSW Section 18 T5N R67W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: Amen #1  
Location ID: 319144



**Photo 1.** Photo taken of the Operator sign at location.



**Photo 2.** Photo taken from the northern location, facing North. Photo illustrates unmanaged weeds.





Inspection Photos  
Location Name: Amen #1  
Location ID: 319144



**Photo 3.** Photo taken from the northern location, facing North.  
See comments under Photo 2.



**Photo 4.** Photo taken from the northern location, facing North.  
See comments under Photo 2.



Inspection Photos  
Location Name: Amen #1  
Location ID: 319144



**Photo 5.** Photo taken from the southern location, facing East.  
See comments under Photo 2.



**Photo 6.** Photo taken from the southern location, facing Northeast. See comments under Photo 2.