

Operator: CRESTONE PEAK RESOURCES OPERATING LLC

Location Name: BARNES-62N67W 4SWSE

Loc ID: 331385

Inspection: 702402297



Exhibit A

CA: Undesirable vegetation growing tall around location ROW. Comply with Rule 606.

CA Resolution: Operator has reported and provided photo evidence the identified vegetation has been addressed and cleared appropriately to comply with Rule 606.