

Interim Reclamation and Stormwater Inspection

August 23, 2023

Operator: KP KAUFFMAN COMPANY INC - 46290

Location ID: 319612

Inspection Document #: 697504812

Weld County, CO

SESW Section 18 T5N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos
Location Name: SPADE-65N67W 18SENW
Location ID: 319612



Photo 1. Photo taken of the Operator sign at the tank battery location. Photo illustrates unmanaged weeds.



Photo 2. Photo taken from the southern tank battery, facing East. See comments under Photo 1.

