

Interim Reclamation and Stormwater Inspection

August 28, 2023

Operator: PHOENIX RESOURCES LLC - #10691

Location ID: 420020

Inspection Document #: 697504826

Weld County, CO

NWNW Section 25 T8N R62W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Cass Farms #11-25H
Location ID: 420020



Photo 1. Photo taken from the entrance of location illustrating the Operator signage.



Photo 2. Photo taken from the northern location, facing East. Photo illustrates unmanaged weeds throughout the location.

Operator has no responded to multiple corrective actions.



Inspection Photos
Location Name: Cass Farms #11-25H
Location ID: 420020



Photo 3. Photo taken from the northern location, facing East.
See comments under Photo 2.



Photo 4. Photo taken from the northern location, facing South.
See comments under Photo 2.