

Operator: CRESTONE PEAK RESOURCES OPERATING LLC

Location Name: IONE 62N66W / NWNE/SEC 2 HZ PAD

Loc ID: 430283

Inspection: 709400389



Exhibit A



Exhibit B



Exhibit C



Exhibit D



Exhibit E



Exhibit F



Exhibit G



Exhibit H

CA: Stormwater erosion onsite and on access road. Comply with Rule 1002.f.

CA Resolution: Operator has reported and provided photo evidence that the identified stormwater erosion onsite has been appropriately addressed and various areas on location have been improved to comply with Rule 1002.f.



Exhibit A

CA: Failure to control and manage weeds to prevent weed waste and prevent the spread of seeds onto adjacent lands. Comply with Rule 606.c.

CA Resolution: Weeds and debris have been appropriately addressed and cleared from the location to comply with Rule 606.c.