

# Interim Reclamation and Stormwater Inspection

August 29, 2023

Operator: CCRP OPERATING INC - #10665

Location ID: 421908

Inspection Document #: 697504828

Weld County, CO

SESW Section 11 T11N R65W


Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
**Oil & Gas Conservation  
Commission**

Department of Natural Resources<sub>S</sub>

Inspection Photos  
Location Name: Wagner #11-65 11-1H  
Location ID: 421908



**Photo 1.** ECMC aerial imagery illustrates the associated access road and location. Red arrow points to Willow Creek with stormwater erosion issues; green arrows indicate approximate weed growth along the access road; red circle indicates the location.



## Inspection Photos

Location Name: Wagner #11-65 11-1H

Location ID: 421908



**Photo 2.** Photo taken from intersection of the access road and Willow Creek, facing West. Photo illustrates stormwater erosion is coming off the access road and causing erosion into the Willow Creek on the southern portion of the access road.



**Photo 3.** Photo taken from intersection of the access road and Willow Creek, facing South. Photo illustrates rill erosion from stormwater runoff from the access road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 697504828



## Inspection Photos

Location Name: Wagner #11-65 11-1H

Location ID: 421908



**Photo 4.** Photo taken from a portion of the access road, facing East. Photo illustrates unmanaged weeds along the access road.



**Photo 5.** Photo taken from location illustrating the well location signage.



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Number: 697504828



## Inspection Photos

Location Name: Wagner #11-65 11-1H

Location ID: 421908



**Photo 6.** Photo taken from the northeastern location, facing Northeast. Photo illustrates unmanaged weeds.



**Photo 7.** Photo taken from the northeastern location, facing North. See comments under Photo 6.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 697504828



## Inspection Photos

Location Name: Wagner #11-65 11-1H

Location ID: 421908



**Photo 8.** Photo taken from the eastern location, facing South. Photo illustrates unmanaged weeds on the topsoil stockpile.



**Photo 9.** Photo taken from the topsoil stockpile. See comments under Photo 8.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 697504828



## Inspection Photos

Location Name: Wagner #11-65 11-1H

Location ID: 421908



**Photo 10.** Photo taken from the southeastern location, facing West. Photo illustrates the location was never interim reclaimed.



**Photo 11.** Photo taken from the southeastern location, facing North. See comments under Photo 10.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 697504828



## Inspection Photos

Location Name: Wagner #11-65 11-1H

Location ID: 421908



**Photo 12.** Photo taken from the southwestern location, facing South. Photo illustrates unmanaged noxious weed growth of cheatgrass, which has already gone to seed.



**Photo 13.** Photo taken from the southwestern location, facing West. See comments under Photo 12.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 697504828



## Inspection Photos

Location Name: Wagner #11-65 11-1H

Location ID: 421908



**Photo 14.** Photo taken from the southwestern location, facing South. Photo illustrates unmanaged weeds.



**Photo 15.** Photo taken from the southwestern location. Photo illustrates unmanaged Canada thistle, a noxious weed, which has gone to seed.



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 697504828