

Inspection Photos
Location Name: Becky 6-36
Location ID: 321348




Photo 1 Undesirable vegetation growing tall along 2 track access road to Location

Photo 2 WH sign.

Inspection Photos
Location Name: Becky 6-36
Location ID: 321348



Photo 3 WH.



Photo 4 Undesirable vegetation growing tall around location ROW.

Inspection Photos
Location Name: Becky 6-36
Location ID: 321348



Photo 5 Undesirable vegetation growing tall around unused transformers.



Photo 6 Undesirable vegetation growing tall around unused transformers.

Inspection Photos
Location Name: Becky 6-36
Location ID: 321348



Photo 7 TB location

Photo 8 TB/sign

Inspection Photos
Location Name: Becky 6-36
Location ID: 321348



Photo 9 TB location

Photo 10 HHS.