

Inspection Photos
Location: State 4-8 Spill
Facility ID: 484923



Photo 1 – Associated Well Site

Photo 2 – Spill Area Looking North

Inspection Photos
Location: State 4-8 Spill
Facility ID: 484923



Photo 3 – Spill Looking East

Photo 4 – Spill Looking South

Inspection Photos
Location: State 4-8 Spill
Facility ID: 484923



Photo 5 – Spill Looking Southwest to Wetland

**Photo 6 – West edge of spill looking west to
Wetland and well pad**

Inspection Photos
Location: State 4-8 Spill
Facility ID: 484923



Photo 7 – Wetland area looking east to spill/release point

Photo 8 – Wetland area looking west toward well site

Inspection Photos
Location: State 4-8 Spill
Facility ID: 484923



Photo 9 – Wetland above pipeline crossing

Photo 10 – Wetland below Pipeline crossing

Inspection Photos
Location: State 4-8 Spill
Facility ID: 484923



Photo 9 – Disturbed soil 1

Photo 10 – Disturbed soil 2

Inspection Photos
Location: State 4-8 Spill
Facility ID: 484923




Photo 9 – Disturbed soil 3




Photo 10 – West Edge of spill is approximately 103 feet for edge of Wetland