

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC YOUBERG RU 13-7 Pad

Location ID: 323944



Photo # 8962 From entrance to location



Photo # 8963 Location

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC YOUBERG RU 13-7 Pad

Location ID: 323944



Photo # 8964 Location

Photo # 8965 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC YOUBERG RU 13-7 Pad

Location ID: 323944



Photo # 3060 From inspection 708900152 conducted on 03/23/2023 Battery sign – some info is illegible



Photo # 8971 Battery sign – some info is illegible

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC YUBERG RU 13-7 Pad

Location ID: 323944



Photo # 8983 Open ended pipe/wildlife hazard



Photo # 8984 Open ended pipe/wildlife hazard

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC YOUBERG RU 13-7 Pad

Location ID: 323944



Photo # 8991 Wildlife netting needs maintenance



Photo # 8992 Wildlife netting needs maintenance

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC YOUNBERG RU 13-7 Pad

Location ID: 323944




Photo # 8995 Unmarked deadman



Photo # 8996 Same unmarked deadman

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC YUBERG RU 13-7 Pad

Location ID: 323944



Photo # 8972 Debris