

Operator: CRESTONE PEAK RESOURCES OPERATING LLC

Location Name: LUHMAN-62N67W 4NESE

Loc ID: 306167

Inspection: 702402299



Exhibit A



Exhibit B



Exhibit C



Exhibit D



Exhibit E



Exhibit F

CA: Undesirable vegetation growing tall and piled up around the WH and TB areas. Comply with Rule 606.

CA Resolution: Field has appropriately addressed the identified overgrowth around the WH and TB areas, and have properly cleared the vegetation to comply with Rule 606. Area will be monitored and maintained moving forward.