

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/13/2023

Submitted Date:

09/13/2023

Document Number:

707601829

FIELD INSPECTION FORM

Loc ID 336634	Inspector Name: Evins, Bret	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 11 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested
------------------	--------------------------------	---	-------------------	---

Operator Information:
 OGCC Operator Number: 100322
 Name of Operator: NOBLE ENERGY INC
 Address: 2001 16TH STREET SUITE 900
 City: DENVER State: CO Zip: 80202

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:			
Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
298201	WELL	TA	10/01/2019	OW	123-29003	SCHMIER B 32-30D	TA
300241	WELL	TA	12/01/2019	OW	123-29659	SCHMIER B 32-31D	TA

General Comment:

This is a WELL inspection.
 Well(s): 2: Temporarily Abandoned | TA.
 Battery: Inactive | Shut-down.

Centralized Battery serves 2 Location IDs
 (336634, 302380).
 (Well(s): 3: Temporarily Abandoned | TA ;1: Plugged & Abandoned | PA).

Centralized Battery formerly served 2 Location IDs
 (305730, 327645).
 (Well(s): 2: Plugged & Abandoned | PA).

Centralized Battery serves 1 Tank Battery Facility ID
 (447717).
 (Battery: Inactive | Shut-down).

Reference:
 A.) Field Inspection Report doc. #707601829 and/or Location ID #336634 for TA Well(s) info. (2).
 B.) Field Inspection Report doc. #707601831 and/or Location ID #302380 for TA Well(s) info. (1).
 C.) Field Inspection Report doc. #707601833 and/or Location ID #336634 for PA Well(s) info. (1).
 D.) Field Inspection Report doc. #707601835 and/or Location ID #305730 for PA Well(s) info. (1).
 E.) Field Inspection Report doc. #707601837 and/or Location ID #327645 for PA Well(s) info. (1).
 F.) Field Inspection Report doc. #707601839 and/or Facility ID #447717 for Battery / Facility, Equipment info.

Location					
Lease Road:					
Type	Access				
comment:	Adequate				
Corrective Action	L				Date:
Overall Good: <input type="checkbox"/>					
Signs/Marker:					
Type	WELLHEAD				
Comment:	2: Wellsites.				
Corrective Action:					Date:
Emergency Contact Number:					
Comment:					
Corrective Action:					Date: _____
Overall Good: <input type="checkbox"/>					
Spills:					
Type	Area	Volume			
In Containment: No					
Comment:					
<input type="checkbox"/> Multiple Spills and Releases?					
Fencing/:					
Type	WELLHEAD				
Comment:	2: Wellsites. Iron panel.				
Corrective Action:					Date:
Equipment:					
Type: Other	# 2				corrective date
Comment:	2: Wellsites. Wellhead w/ Master, casing valves.				
Corrective Action:					Date:
Type: Bradenhead	# 2				
Comment:	2: Wellsites. Appears plumbed to surface.				
Corrective Action:					Date:
Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.359546,-104.582714
Comment:	Centralized Battery serves 2 Location IDs (336634, 302380). (Well(s): 3: Temporarily Abandoned TA). Centralized Battery serves 1 Tank Battery Facility ID (447717). (Battery: Inactive Shut-down).				
Corrective Action:					Date:

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 298201 Type: WELL API Number: 123-29003 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA.
Disconnected from flowlie.
Locked-Out, Tagged-Out | LOTO.
Blue TA tag posted.
CECMC records last prod: 03/2019.

Form 4 on file. TA date: 04/22/2019. Approved.
DH-CIBP set.
Form 21 MIT on file. MIT date: 10/31/2019. Approved.
Form 6A on file. Out-of-Svc Designation.
Date: 10/17/2019. Approved.

Corrective Action: _____ Date: _____

BradenHeadDate of Last Brhd Test: 07/01/2023 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

Facility ID: 300241 Type: WELL API Number: 123-29659 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____

Comment: Temporarily Abandoned | TA.
Disconnected from flowlie.
Locked-Out, Tagged-Out | LOTO.
Blue TA tag posted.
CECMC records last prod: 03/2019.

Form 4 on file. TA date: 05/22/2019. Approved.
DH-CIBP set.
Form 21 MIT on file. MIT date: 10/31/2019. Approved.
Form 6A on file. Out-of-Svc Designation.
Date: 09/28/2021. Approved.

Corrective Action: _____ Date: _____

BradenHeadDate of Last Brhd Test: 07/09/2023 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>CECMC Inspection Report Summary:</p> <p>On WED 09/13/2023 at approximately 14:14 hrs. I, Bret Evins, conducted an onsite inspection at: Operator Name: NOBLE ENERGY INC Location Name: SCHMIER-65N64W/32NWNW Location ID: 336634 Well Name(s): Schmier B 32-30D, Schmier B 32-31D. API: 123-29003, 123-29659. Location County: Weld County, Colorado Weather: Mostly Sunny, dry.</p> <p>While there, I observed: Well(s): 2: Temporarily Abandoned TA. Battery: Inactive Shut-down.</p> <p>Centralized Battery serves 2 Location IDs (336634, 302380). (Well(s): 3: Temporarily Abandoned TA ;1: Plugged & Abandoned PA).</p> <p>Centralized Battery formerly served 2 Location IDs (305730, 327645). (Well(s): 2: Plugged & Abandoned PA).</p> <p>Centralized Battery serves 1 Tank Battery Facility ID (447717). (Battery: Inactive Shut-down).</p> <p>Reference: A.) Field Inspection Report doc. #707601829 and/or Location ID #336634 for TA Well(s) info. (2). B.) Field Inspection Report doc. #707601831 and/or Location ID #302380 for TA Well(s) info. (1). C.) Field Inspection Report doc. #707601833 and/or Location ID #336634 for PA Well(s) info. (1). D.) Field Inspection Report doc. #707601835 and/or Location ID #305730 for PA Well(s) info. (1). E.) Field Inspection Report doc. #707601837 and/or Location ID #327645 for PA Well(s) info. (1). F.) Field Inspection Report doc. #707601839 and/or Facility ID #447717 for Battery / Facility, Equipment info.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	09/13/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
707601830	Site photo(s)	http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6250181